

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/16/2022

Submitted Date:

09/16/2022

Document Number:

699804930

FIELD INSPECTION FORM

Loc ID 334780 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: PO BOX 370
 City: PARACHUTE State: CO Zip: 81635

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456921	Domestic Tap	AC	08/28/2018		-	Domestic Tap 33NESW	AC

General Comment:

[COGCC Inspection Report Summary](#)
 On Thursday 9/15/22 at approximately 14:30 hours, I, Inspector Corey De Paolo, Conducted a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap #33NESW. Location #456921 in Garfield County Colorado.
 While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a big Joe regulator. Following regulator there is an in line odorizer followed by another little Joe regulator. All fittings appear to be adequately sized to handle the maximum operating pressures of the regulators.
 This is a summary of inspection report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: [Pipe rail fence around domestic tap](#)

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Inspected Facilities

Facility ID: 456921 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a big Joe regulator. Following regulator there is an in line odorizer followed by another little Joe regulator. All fittings appear to be adequately sized to handle the maximum operating pressures of the regulators.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Gravel						
		Compaction				
Berms						
		Culverts				

Comment: [Refer to document #699804926 for storm water comments.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for comments	depaoloc	09/16/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804931	Photos for Insp. #699804930	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5862750