

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2022

Submitted Date:

09/15/2022

Document Number:

700704570

FIELD INSPECTION FORMLoc ID 316764 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|-----------------------|---------------------------------|
| Trujillo, Helen | | notices@rlbayless.com | All inspections |
| Thomas, John | 505-326-2659 | jthomas@rlbayless.com | all inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 232726 | WELL | SI | 08/01/2021 | OW | 107-06140 | DRY CREEK FEDERAL 1-14 | SI |

General Comment:**COGCC Inspection Report Summary**

On Monday 9/5/2022 at approximately 1400, I, Inspector Scott Ramsey, conducted an inspection on site in response of Complaint from wild earth guardians at Robert Bayless Dry Creek Federal 1-14, at Location # 316764 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed NO evidence of gas leak located with OGI camera.

During this inspection the following possible compliance issues were observed:

1. Load lines missing caps/plugs
2. Well is lacking API # and access road information
3. Tanks are missing operator information
4. Random staining
5. Random debris

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

| Location | | | | |
|---|---|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | BATTERY | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type | CONTAINERS | | | |
| Comment: | Propane tank lacking labeling | | | |
| Corrective Action: | Provide proper labeling | | | Date: 10/06/2022 |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | Tanks are missing operator information | | | |
| Corrective Action: | Provide proper labeling | | | Date: 10/27/2022 |
| Type | WELLHEAD | | | |
| Comment: | Well is lacking API # and access road information | | | |
| Corrective Action: | Provide proper labeling | | | Date: 10/27/2022 |
| Emergency Contact Number: | | | | |
| Comment: | 911 | | | |
| Corrective Action: | | | | Date: _____ |
| Good Housekeeping: | | | | |
| Type | DEBRIS | | | |
| Comment: | Random debris | | | |
| Corrective Action: | Remove all debris | | | Date: 10/06/2022 |
| Type | OTHER | | | |
| Comment: | Guard missing from pump jack | | | |
| Corrective Action: | Install proper protection | | | Date: 10/06/2022 |
| Type | OTHER | | | |
| Comment: | Random staining | | | |
| Corrective Action: | Remove all stained material | | | Date: 10/06/2022 |
| Type | OTHER | | | |
| Comment: | Load lines missing caps/plugs | | | |
| Corrective Action: | Install caps/plugs | | | Date: 10/06/2022 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| Equipment: | | | corrective date |
|-----------------------|-----|-------|-----------------|
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: Well head | | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|---------------------------|---|-----------|-----------|---------|--------|
| OTHER | 1 | <100 BBLS | STEEL AST | | , |
| Comment: 90 BBL Vent tank | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|--------|
| Earth | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 3 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Inspector Name: Ramsey, Scott

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected FacilitiesFacility ID: 232726 Type: WELL API Number: 107-06140 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last produced 7/2021

Corrective Action: _____

Date: _____

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Calm Speed: _____ (mph) Direction From: _____ Weather: Clear Temperature: 90 (F)Assisting Staff Mike Longworth Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

| Time Survey Start | AM/PM | Time Survey End | AM/PM |
|-------------------|-------|-----------------|-------|
| 2:20 | PM | 3:00 | PM |

| Equipment |
|----------------------|
| Wellhead(s) |
| Oil Tank(s) |
| Separation Equipment |

Comment: No leaks observed with OGICorrective
Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------|---|
| 700704575 | FLIR video for complaint | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5862788 |
| 700704576 | Photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5862789 |