

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2022

Submitted Date:

09/16/2022

Document Number:

690103192

FIELD INSPECTION FORMLoc ID 336252 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250098	WELL	TA	02/10/2022	OW	123-17901	WADDLE 24-10J7	PA
262139	WELL	PR	04/01/2019	GW	123-20707	MAGNESS 14-24A	SI
445530	TANK BATTERY	AC	04/20/2016		-	BIRKLE-63N67W 24SWSE	EG
482910	SPILL OR RELEASE	CL			-	Waddle 24-10J7 Wellhead	EG

General Comment:COGCC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 250098 Type: WELL API Number: 123-17901 Status: TA Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Waddle 24-10J7) has been plugged and abandoned; cut and cap work is completed. COGCC form 42 notice of start of plugging operations doc #402832683 received 10/06/2021. The wellhead flowline (OLF) removal/ AIP work is in progress. Flowline riser observed in fenced excavation at inlet to HHS; no riser observed at fenced WH excavation. COGCC form 42 notice of flowline abandonment completed doc #403152141 received on 08/31/2022. Facility/ battery services (2) additional wells (SI); Excavation/ remediation work is in progress. No Oxy or contract personnel were on location at time of inspection.

Corrective Action:

Date:

Facility ID: 262139 Type: WELL API Number: 123-20707 Status: PR Insp. Status: SI

Facility ID: 445530 Type: TANK API Number: - Status: AC Insp. Status: EG

Facility ID: 482910 Type: SPILL OR API Number: - Status: CL Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403150392 received on 09/01/2022: During plugging and abandonment activities at the Waddle 24-10J7 wellhead, historically impacted soil in contact groundwater was discovered adjacent to the wellhead. The volume of the release is unknown.	maclarej	09/16/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103194	Excavation at PA wells; view N to battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5862839
690103195	Excavation and isolated FL risers at HHS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5862840
690103196	Signage at tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5862841