

Final Reclamation and Stormwater Inspection

Date: 09/13/2022

Operator: AXIS EXPLORATION LLC - 10646

Location ID: 320193

Inspection Document #: 696105424

Adams County, CO

SWSW Section 5 T3S R64W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 1. Tank battery location photo taken from northwest corner, facing southeast. Location has not been reclaimed; annual weedy vegetation observed and outlined in red (russian thistle).

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 2. Facing south from northern portion of location, see comments in photo 1.

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 3. Facing north from southern portion of location, see comments in photo 1.

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 4. Facing northwest from southern portion of location, see comments in photo 1.

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 5. Photo taken from northern portion, facing east. Photo illustrates access road has not been reclaimed with presence of annual weedy vegetation (e.g. russian thistle, kochia, field bindweed) and non-uniform vegetation cover resulting in bare soil. Reference area is wheat stubble.

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 6. Well location photo taken from northern portion, facing southeast. Photo illustrates presence of annual weedy vegetation including kochia, russian thistle, and field bindweed (CO List C Noxious Weed). The eastern portion of the disturbance area drops off and is not recontoured, arrow in red.

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 7. Facing south, see comments in photo 6.

Inspection Photos
Location Name: QUALLS #5-13
Location ID: 320193



Photo 8. Facing west, see comments in photo 6.