

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2022

Submitted Date:

09/19/2022

Document Number:

697006450

FIELD INSPECTION FORM

Loc ID 159823 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159820	WELL	PR	07/18/2017	OW	123-41052	WILSON RANCH 33C-27HZ	PR
159828	WELL	PR	07/03/2017	OW	123-41053	WILSON RANCH 13N-27HZ	PR
159847	WELL	SI	06/01/2022	OW	123-41065	WILSON RANCH 34N-27HZ	SI
159848	WELL	PR	05/01/2019	OW	123-41066	WILSON RANCH 34C-27HZ	PR
159849	WELL	PR	07/04/2017	OW	123-41067	WHISPER ROCK 8N-25HZ	PR
159850	WELL	PR	07/04/2017	OW	123-41068	WHISPER ROCK 9N-25HZ	PR
159851	WELL	PR	07/03/2017	OW	123-41069	WHISPER ROCK 4C-25HZ	PR
159852	WELL	PR	07/01/2017	OW	123-41070	WHISPER ROCK 10N-25HZ	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical systems		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 8		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Frac valve wheel next to Whisper Rock 8N-25HZ wellhead, see attached photo.		
Corrective Action:	Comply with Rule 606	Date:	10/07/2022

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Pipe fencing		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	#		
Comment:	Automation array, electrical systems, chemical systems in secondary containment, supplied air compressor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: LACT	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 4		
Comment:	Electric motors on LACT, supplied air compressor and pump jack		
Corrective Action:			Date:
Type: Gathering Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Pilot is on		
Corrective Action:			Date:
Type: Flow Line	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	OTHER	STEEL AST		
-----------	---	-------	-----------	--	--

Comment:	286 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	STEEL AST		

Comment:	286 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO				
Comment:					
Corrective Action:					Date:

Flaring:

Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 159820 Type: WELL API Number: 123-41052 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/07/2022 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 27 Fluid Type: None
 End Surf Csg Pressure: --
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 159828 Type: WELL API Number: 123-41053 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/12/2022 Annual Brhd Completed? _____
 Last Brhd Test Results Initial Surf Csg Pressure: 13 Fluid Type: WATER H2O
 End Surf Csg Pressure: 1
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 159847 Type: WELL API Number: 123-41065 Status: SI Insp. Status: SI

Producing Well

Comment: _____
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/08/2022 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None
 End Surf Csg Pressure: --
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 159848 Type: WELL API Number: 123-41066 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/10/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date: _____

Facility ID: 159849 Type: WELL API Number: 123-41067 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/07/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date: _____

Facility ID: 159850 Type: WELL API Number: 123-41068 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/01/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date: _____

Facility ID: 159851 Type: WELL API Number: 123-41069 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/08/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 45 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date: _____

Facility ID: 159852 Type: WELL API Number: 123-41070 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/10/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 9/19/2022 at approximately 12:00 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Anadarko Wilson Ranch 34N-27HZ Pad location #159823 in Weld County, Colorado. While there, I observed unused equipment on location. During this inspection the following possible compliance issues were observed: Rule 606. with a corrective action date of 10/7/2022. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	09/19/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697006451	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5864017