

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /29NENW

Location ID: 335088



Photo #7711 From entrance to location.



Photo #7712 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /29NENW

Location ID: 335088



Photo #7713 Rill erosion.



Photo #7714 Rill erosion.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /29NENW

Location ID: 335088



Photo #7715 Run on to location is not being controlled.



Photo #7716 Sediment is encroaching on equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /29NENW

Location ID: 335088



Photo #7717 Rill erosion.



Photo #7718 Rill erosion.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON-66S96W /29NENW

Location ID: 335088



Photo #7719 Rill erosion.