

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2022

Submitted Date:

09/19/2022

Document Number:

699804934

**FIELD INSPECTION FORM**

Loc ID: 324097    Inspector Name: De Paolo, Corey    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE    State: CO    Zip: 81635

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456945	Domestic Tap	AC	08/28/2018		-	Domestic Tap 29SESE	AC

**General Comment:**

COGCC Inspection Report Summary  
On Thursday 9/15/22 at approximately 15:30 hours, I, Inspector Corey De Paolo, Conducted a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap 29SESE. Location #324097 in Garfield County Colorado.  
While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a big Joe regulator. Following the regulator there is an in line odorizer followed by a fluid knock out. All fittings appear to be adequately sized to handle the maximum operating pressures of the regulators.  
This is a summary of inspection report.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type OTHER

Comment: Hog panels around Domestic tap

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 456945 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a big Joe regulator. Following the regulator there is an in line odorizer followed by a fluid knock out. All fittings appear to be adequately sized to handle the maximum operating pressures of the regulators.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Compaction				
		Berms				
Compaction						

Comment: [Refer to document #699804934 for storm water inspection](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Storm water for comments</a>	depaoloc	09/19/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804935	Photos for Insp. #699804934	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5866013">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5866013</a>