

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403170608

Date Received:  
09/19/2022

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10766  
Name of Operator: ARKOMA OPERATIONS LLC  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Price, Andrew</u>	<u>918-260-8324</u>	<u>aprice@arkomaops.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500445  
Inspection Date: 09/13/2022 FIR Submit Date: 09/13/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ARKOMA OPERATIONS LLC Company Number: 10766  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 311923

Location Name: MCELVAIN-HARMON-N33N8W Number: 19NWNE County: LA PLATA  
Qtrqr: NWNE Sec: 19 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.093840 Longitude: -107.755580

FACILITY - API Number: 05-067-00 Facility ID: 89089

Facility Name: MCELVAIN-HARMON Number: 1A  
Qtrqr: NWNE Sec: 19 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.093840 Longitude: -107.755580

CORRECTIVE ACTIONS:

1 ☒ CA# 164540

Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C Date: 11/13/2022

Response: CA COMPLETED Date of Completion: 09/15/2022

Operator Comment: There were storm water erosion channels forming near wellhead, near produced water tank, and near gas meter run. We filled in storm water channels and fixed the the run of the storm water to try and stop the erosion.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500445 has been satisfactorily completed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: There were storm water erosion channels forming near wellhead, near produced water tank, and near gas meter run. We filled in storm water channels and fixed the the run of the storm water to try and stop the erosion.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: \_\_\_\_\_

Title: Engineering Analyst

Date: 9/19/2022 1:25:54 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403170608	FIR RESOLUTION SUBMITTED
403170614	McElvain-Harmon 1A Remedial Report

Total Attach: 2 Files