

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2022

Submitted Date:

09/15/2022

Document Number:

700704570

FIELD INSPECTION FORM

 Loc ID 316764 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 6720
 Name of Operator: ROBERT L BAYLESS PRODUCER LLC
 Address: 621 17TH ST STE 2300
 City: DENVER State: CO Zip: 80293
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Thomas, John	505-326-2659	jthomas@rlbayless.com	all inspections
Trujillo, Helen		notices@rlbayless.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232726	WELL	SI	08/01/2021	OW	107-06140	DRY CREEK FEDERAL 1-14	SI

General Comment:**COGCC Inspection Report Summary**

On Monday 9/5/2022 at approximately 1400, I, Inspector Scott Ramsey, conducted an inspection on site in response of Complaint from wild earth guardians at Robert Bayless Dry Creek Federal 1-14, at Location # 316764 in Route county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed NO evidence of gas leak located with OGI camera.

During this inspection the following possible compliance issues were observed:

1. Load lines missing caps/plugs
2. Well is lacking API # and access road information
3. Tanks are missing operator information
4. Random staining
5. Random debris

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location				
Lease Road:				
	Type	Access		
	comment:			
	Corrective Action	L	Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
	Type	BATTERY		
	Comment:			
	Corrective Action:		Date:	
	Type	WELLHEAD		
	Comment:	Well is lacking API # and access road information		
	Corrective Action:	Provide proper labeling	Date:	10/27/2022
	Type	TANK LABELS/PLACARDS		
	Comment:	Tanks are missing operator information		
	Corrective Action:	Provide proper labeling	Date:	10/27/2022
	Type	CONTAINERS		
	Comment:	Propane tank lacking labeling		
	Corrective Action:	Provide proper labeling	Date:	10/06/2022
Emergency Contact Number:				
	Comment:	911		
	Corrective Action:		Date:	_____
Good Housekeeping:				
	Type	OTHER		
	Comment:	Load lines missing caps/plugs		
	Corrective Action:	Install caps/plugs	Date:	10/06/2022
	Type	OTHER		
	Comment:	Random staining		
	Corrective Action:	Remove all stained material	Date:	10/06/2022
	Type	OTHER		
	Comment:	Guard missing from pump jack		
	Corrective Action:	Install proper protection	Date:	10/06/2022
	Type	DEBRIS		
	Comment:	Random debris		
	Corrective Action:	Remove all debris	Date:	10/06/2022
Overall Good: <input type="checkbox"/>				
Spills:				
	Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment: Well head			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<100 BBLs	STEEL AST		,
Comment: 90 BBL Vent tank					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 232726 Type: WELL API Number: 107-06140 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

