

# Cover Data

Date: 9/16/22

Inspected By: Anna O'Malley

Location/Operator: 466705/Gulf Exploration LLC

Transect #/disturbed/Ref	D1		R1						
Transect Orientation and first photo, degrees	87°(E)		88°(E)						
Photo Midpoint (2)									
End transect									
Photo other									
Aspect/Slope	East /w 5%		East /w 5%						
		Totals		Totals		Totals		Totals	
Cryptogams (eg. Moss, lichen)	0%		2%						
Litter	36%		14%						
Bare Soil	4%		33%						
Rock	0%		1%						
★ Total Weeds	39%		0%						
Total Desirable Species	21%		46%						
80% Check	(21/46) = 46% of reference - Fail								
	1st Hit	2nd/P	1st Hit	2nd/P	1st Hit	2nd/P	1st Hit	2nd/P	
Bare Soil	::		☒☒☒::						
Litter	☒☒☒☒:		☒::						
Rock			°						
PG <i>Pascopyrum smithii</i>	☒☒		::						
★ <i>Bromus tectorum</i>	☒☒☒☒								
PG <i>Pseudoroegneria spicata</i>									
SH <i>Chrysothamnus viscidiflorus</i>			☒						
SH <i>Artemisia tridentata</i> var. <i>vaseyana</i>			☒☒:						
Moss			°						
PG <i>Sedum lanceolatum</i>			°						
PG <i>Koeleria macrantha</i>			☐						
AF <i>Cordylanthus ramosus</i>			::						
Lichen			°						
PG <i>Hesperostipa comata</i>			°						
PG <i>Achnatherum lettermanii</i>			°						

2nd= second hit; P= plant species present but not hit