

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2022

Submitted Date:

09/23/2022

Document Number:

702500469**FIELD INSPECTION FORM**Loc ID 334008 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297399	WELL	PR	07/14/2021	GW	067-09610	ZELLITTI A 4	PR
297400	WELL	PR	07/28/2008	CBM	067-09611	PHILLIPS A 4	PR

General Comment:

Inspector Alex Klink on site to conduct follow up inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

At time of inspection spill prevention for compressor station was less than 1" from being overtopped with oily fluid and rainwater. Simcoe contact was called and notified.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	At time of inspection spill prevention for compressor station was less than 1" from being overtopped with oily fluid and rainwater. (IMG 05).		
	CA from previous inspection Doc# 702500246 has been satisfactorily completed.		
Corrective Action:	Remove oily fluid and rainwater from spill prevention to prevent pollutants from impacting surface material per rule 1002. Dispose of in an approved manner.	Date:	09/25/2022
Type	UNUSED EQUIPMENT		
Comment:	CA from previous inspection Doc# 702500246 has been satisfactorily completed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 297399 Type: WELL API Number: 067-09610 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 297400 Type: WELL API Number: 067-09611 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500470	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5868817