

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2022

Submitted Date:

09/23/2022

Document Number:

702500479

**FIELD INSPECTION FORM**

Loc ID 325777 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	<a href="#">All SW field inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215367	WELL	PR	07/01/2021	GW	067-06972	SIMON LAND & CATTLE 27-01 1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well sign lists previous operator, BP America Production Company (IMG 01).		
Corrective Action:	Install sign with current operator to comply with Rule 605.a.	Date:	11/23/2022

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	Equipment on this location is enclosed by stock panel.		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Prime Mover	# 1		
Comment:	Electric		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Telemetry, electric cabinet, electric meter, pump control panel, valve cluster pit		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Linear rod pump		
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	3" line from wellhead to separator, 2" line from separator to gas meter run, 2" line from separator to produced water off location.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment: Bradenhead is accessible.			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment: Separator vent stack is screened properly.			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215367 Type: WELL API Number: 067-06972 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Compaction	Pass			
		Gravel	Pass			
Compaction	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500480	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5868822">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5868822</a>