

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/21/2022

Submitted Date:

09/21/2022

Document Number:

695106753**FIELD INSPECTION FORM**Loc ID 422128 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10417Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLCAddress: 113 N SANTA FE AVECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Tim		thart@fremontpetroleum.com	<a href="#">All inspections</a>
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@austineexploration.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422130	WELL	PR	10/01/2020	OW	043-06202	Elliot Ness 22-17	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Other

# 1

Comment: PROPANE TANK

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	FIBERGLASS AST		38.395903,-105.136415
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 422130 Type: WELL API Number: 043-06202 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Complaint**

Comment:

Inspection in response to complaint.  
 Field Inspector Assigned: Tom Beardslee  
 Complaint Received  
 Date: 9-8-2022  
 Complaint Contacted:  
 Date: 9-14-2022 Time: 3:30 PM via phone left voice mail, received a call back @ 4:00 PM  
 Location ID # 422130  
 Location name: Eliot Ness 22-17  
 Inspection Document # 695106753  
 Complaint Document #4031600369  
 Nature of Complaint: GAS LEAK  
 Field Inspector Actions:  
 On 9-8-2022, I Tom Beardslee area field inspector was assigned a complaint received by COGCC staff in reference to gas leaking from oil tank battery. The complainant (Andrew Klooster) stated the issues were occurring out of the 2" on top of both crude oil tanks on location.  
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, a FLIR video showed no leaks near tanks or wellhead.  
 No COGCC rule violations were witnessed at time of inspection.  
 Weather conditions: cloudy light gusting wind up to app. 15 mph.  
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: SUBMIT FORMS

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**Survey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 38.395903 Long: -105.136415Wind: Light Speed: 4 (mph) Direction From: SOUTH Weather: Cloudy Temperature: 72 (F)Assisting Staff Randy Silver Camera #: \_\_\_\_\_☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
10:40	AM	10:42	AM

Equipment
Wellhead(s)
Oil Tank(s)

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
INSPECTION DUE TO COMPLAINT #403160369, AT TIME OF INSPECTION I DID NOT WITNESS ANY VENTING ON LOCATION. it appears that the backside is plumbed to tank battery with a buried 1" line. At time of inspection the 1" line is closed.	beardslt	09/21/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695106754	INSP PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5871180">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5871180</a>
695106755	FLIRR VIDEO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5871181">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5871181</a>