

Inspection Photos

API: 071-08769

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08769 | Date: 9/23/2022

Inspection Photos



Photo 1. This culvert inlet was cleaned out however, the culvert is full of sediment. Previous corrective action was not completed. Lat/Long:37.00581,-104.83861.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2022

Inspection Photos



Photo 2. The main road has recently been graded including the access road to a nearby wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2022

Inspection Photos



Photo 3. There is an erosion gully along the road that needs to be repaired and stabilized. Previous corrective action was not completed. Red arrow points to 4.5 ft. shovel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2022

Inspection Photos



Photo 4. The side of the road is eroded and not stabilized. This area needs to be repaired and stabilized. Previous corrective action not completed. Red arrow points to 4.5 ft. shovel. Lat/Long:36.99952,-104.83425.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2022

Inspection Photos



Photo 5. The side of the road is eroded and not stabilized. Erosion head cutting is continuing to occur further back. This area needs to be repaired and stabilized. Previous corrective action not completed. Red arrow points to 4.5 ft. shovel. Lat/Long:36.99952,-104.83425. There are also noxious shown in the photo.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2022

Inspection Photos



Photo 6. Further along the road near the Colorado line. The roadside and road is eroded and needs to be repaired and stabilized. Red arrow points to 4.5 ft. shovel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2022

Inspection Photos



Photo 7. This culvert inlet was cleaned out however, the culvert is full of sediment which needs to be cleaned out. Lat/Long:36.99405,-104.84710.

Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2022

Inspection Photos



Photo 8. Facing northeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08769 | Date: 9/23/2022