

Inspection Photos

ID: 412161

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID:412161 | Date: 9/23/2022

Inspection Photos



Photo 1. Facing northwest at the disturbance along the gathering pipeline at Lat/Long:37.05440,-104.76614. This area has been reseeded however, soils are not stabilized and there is now erosion occurring. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 9/23/2022

Inspection Photos



Photo 2. Facing southeast along the pipeline disturbance. There are signs of erosion occurring. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 9/23/2022

Inspection Photos




Photo 3. Facing northwest along the pipeline disturbance. There are noxious weeds beginning to establish which must be controlled. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 9/23/2022

Inspection Photos



Photo 4. View of some of the erosion occurring. Additional BMP's are needed to prevent erosion. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 9/23/2022

Inspection Photos



Photo 5. There was disturbance that occurred along the main road that needs to be seeded and stabilized. Lat/Long:37.05647,-104.76314.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 9/23/2022

Inspection Photos



Photo 6. Facing toward the VPRC CENTRAL FACILITY UNIT C-3.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:412161 | Date: 9/23/2022