

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/28/2022

Submitted Date:

09/28/2022

Document Number:

702500500

FIELD INSPECTION FORMLoc ID 326474 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216553	WELL	PR	01/01/2003	CBM	067-08159	TENORIO 3-32	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Lube oil from pump jack prime mover has stained concrete pad and impacted surface material (IMG 05).

Corrective Action:

Remove oily residue and impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 10/13/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

PUMP JACK

Comment:

Pump jack enclosed by stock panel.

Corrective Action:

Date:

Equipment:

corrective date

Type: Gas Meter Run

1

Comment:

Gas meter is calibrated within the last year.

Corrective Action:

Date:

Type: Vertical Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Flow Line

4

Comment:

3" line from wellhead to separator, 4" line from gas meter run to off location, 3" produced water line from separator to off location, 1" line from separator to gas powered prime mover.

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Gas powered

Corrective Action:

Date:

Type: Bird Protectors

1

Comment:

Separator vent stack is screened properly

Corrective Action:

Date:

Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Rig anchors not marked properly (IMG 03 and IMG 04).		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	10/13/2022

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 216553	Type: WELL	API Number: 067-08159	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	
		Culverts	Pass			
		Gravel	Pass			
		Compaction	Pass			
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500501	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5872742