

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2022

Submitted Date:

09/28/2022

Document Number:

701005805

FIELD INSPECTION FORM

Loc ID 303527 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	(970) 332-3585	pat.dolezal@ownresources.com	
Sharp, Kelly	(970) 630-6880	kelly.sharp@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253242	WELL	PR	08/01/2019	GW	125-07119	ECKLEY OIL & LAND 2-13	PR

General Comment:

[Routine Inspection](#)

Location			
Lease Road:			
	Type Access		
	comment: Gravel road through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
	Type TANK LABELS/PLACARDS		
	Comment: Metal sign by water tank		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment: Lease sign by meter shed		
Corrective Action:			Date:
Emergency Contact Number:			
	Comment:		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
	Comment: _____		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
	Type PUMP JACK		
	Comment: Wire paenls around wellhead and meter shed		
Corrective Action:			Date:
	Type TANK BATTERY		
	Comment: Metal panels around water tank		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 253242 Type: WELL API Number: 125-07119 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Welp 33-13, 34-13 & Eckley Oil & Land 2-13\) 2200' S @ 39.88010/-102.24566](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: [Location and access have erosion and need maintenance](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701005827	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5873018