

Inspection Photos

API: 071-06819

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06819 | Date: 9/23/2022

Inspection Photos



Photo 1. Facing southeast along the access road. The road has recently been graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06819 | Date: 9/23/2022

Inspection Photos



Photo 2. The grading of the road pushed over these large oaks causing additional disturbance and widening of the road. The tree debris will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06819 | Date: 9/23/2022

Inspection Photos



Photo 3. Facing back to the north facing down toward the access road. There are no BMP's along the road side to prevent erosion along the long steep grade of the road. Stormwater will cause erosion of the roadside and BMP's must be installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06819 | Date: 9/23/2022

Inspection Photos



Photo 4. Facing northwest toward the wellsite. There are exposed electric lines on the surface. The lines need to be removed or repaired and protected. This area of disturbance needs to be seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06819 | Date: 9/23/2022

Inspection Photos



Photo 5. Facing northwest toward the wellsite.

