

Construction and Stormwater Inspection

September 21, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 478972

Inspection Document #:697504203

Weld County, CO

NENW Section 36 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GADDIS /3-36HZ PAD
Location ID: 478972



Photo 1. Photo taken from the entrance of location. Photo illustrates the Operator sign and mailbox. This mailbox only had the Weld County Grading permit.



Photo 2. Photo taken from the entrance of location, facing East. Photo illustrates mailbox was open and without the required permits.

Inspection Photos
Location Name: GADDIS /3-36HZ PAD
Location ID: 478972



Photo 3. Photo taken from the eastern location, facing North. Photo illustrates a ditch and berm BMP installed around the perimeter of location which is directed to a retention area.



Photo 4. Photo taken from the eastern location, facing East. Photo illustrates the overflow outlet. Stormwater discharge would not be accepted into the irrigation ditch.

Inspection Photos
Location Name: GADDIS /3-36HZ PAD
Location ID: 478972



Photo 5. Photo taken from the southeastern location, facing Southwest. Photo illustrates the topsoil stockpile has been seeded and straw crimped with mulch. However, the straw crimped mulch has blown off most of the stockpile; therefore, CDPHE is requiring a corrective action.



Photo 6. Photo taken from the southeast location, facing West. Photo illustrates the retention area.

Inspection Photos
Location Name: GADDIS /3-36HZ PAD
Location ID: 478972



Photo 7. Photo taken from the northwestern location, facing North. Photo illustrates the cut slope may need further stabilization to ensure long-term stabilization.



Photo 8. Photo taken from the northwestern location, facing Southeast. See comments under Photo 7.