

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BROOME-66S91W /30SESE

Location ID: 335227



Photo #7795 From entrance to location.



Photo #7796 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BROOME-66S91W /30SESE

Location ID: 335227



Photo #7797 From entrance to location.



Photo #7798 Unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BROOME-66S91W /30SESE

Location ID: 335227



Photo #7799 Unused equipment.



Photo #7800 Rill erosion occurring on cut slope.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BROOME-66S91W /30SESE

Location ID: 335227



Photo #7801 Run on to location is not being controlled.



Photo #7802 Run on to location is not being controlled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BROOME-66S91W /30SESE

Location ID: 335227



Photo #7803 Rill erosion occurring on cut slope.