

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU-66S93W /23SENE

Location ID: 335444



Photo #7829 From entrance to location.



Photo #7830 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU-66S93W /23SENE

Location ID: 335444



Photo #7831 From entrance to location.



Photo #7832 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU-66S93W /23SENE

Location ID: 335444



Photo #7833 Location lacks stabilization.



Photo #7835 Insufficient tracking BMP at entrance to location