

Inspection Photos

Location Name: CAERUS PICEANCE LLC BJM-66S92W /30L4NW

Location ID: 335401



Photo #7841 From entrance to location.



Photo #7842 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC BJM-66S92W /30L4NW

Location ID: 335401



Photo #7843 From entrance to location.



Photo #7844 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC BJM-66S92W /30L4NW

Location ID: 335401



Photo #7845 Location lacks stabilization.



Photo #7846 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC BJM-66S92W /30L4NW

Location ID: 335401



Photo #7847 Location lacks stabilization.



Photo #7850 Insufficient tracking BMP at entrance to location