

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-67S92W /8NWSE

Location ID: 334821



Photo #7856 From entrance to location.



Photo #7857 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-67S92W /8NWSE

Location ID: 334821



Photo #7858 From entrance to location.



Photo #7859 Multiple places with heating insulation open ended and not capped.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-67S92W /8NWSE

Location ID: 334821



Photo #7860 Multiple places with heating insulation open ended and not capped.



Photo #7861 Multiple places with heating insulation open ended and not capped.