

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/28/2022

Submitted Date:

09/29/2022

Document Number:

699804975

FIELD INSPECTION FORMLoc ID 335467 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293618	WELL	PR	06/19/2008	GW	045-15071	GGU VAN ORDSTRAND 23B-30-691	PR
293625	WELL	SI	02/01/2022	GW	045-15072	GGU VANORDSTRAND 33D-30-691	SI
293626	WELL	PR	06/23/2008	GW	045-15073	GGU VANORDSTRAND 23C-30-691	PR
293627	WELL	PR	06/10/2008	GW	045-15074	GGU VANORDSTRAND 33B-30-691	PR
293629	WELL	PR	06/22/2008	GW	045-15075	GGU VANORDSTRAND 23D-30-691	PR
293632	WELL	PR	06/01/2017	GW	045-15076	GGU VANORDSTRAND 34D-30-691	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 9/27/22 at approximately 15:00 hours, I, Inspector Corey De Paolo,

Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC GGU VAN ORDSTRAND-66S91W /30NESW.

Location #335467 in Garfield County Colorado.

Refer to document #700704130 inspection conducted on 4/28/22. Previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Unused equipment with a corrective action date of 10/5/22.

2) Undesirable plant species in tank containment with a corrective action date of 10/5/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Undesirable plant species in tank containment.		
Corrective Action:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.	Date:	10/05/2022
Type	STORAGE OF SUPL		
Comment:	Unused equipment.		
Corrective Action:	The storage of equipment not necessary for use on location is prohibited.	Date:	10/05/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Livestock panels.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	SEPARATOR		

Comment: Livestock panels			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Plunger Lift	# 6		
Comment: All wells on plunger lift			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment: Chemical tanks			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment: Taylor plugs located on braden head. All braden head valves are accessible.			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Centralized containment					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 293618	Type: WELL	API Number: 045-15071	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:		Date:		
Facility ID: 293625	Type: WELL	API Number: 045-15072	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last produced January 2022				
Corrective Action:		Date:		
Facility ID: 293626	Type: WELL	API Number: 045-15073	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:		Date:		
Facility ID: 293627	Type: WELL	API Number: 045-15074	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:		Date:		
Facility ID: 293629	Type: WELL	API Number: 045-15075	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:		Date:		
Facility ID: 293632	Type: WELL	API Number: 045-15076	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:		Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Berms				
		Berms				
Gravel						
Sediment Traps						
		Compaction				
Compaction						
		Sediment Traps				
Ditches						
Berms						
		Culverts				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to housekeeping for corrective actions.	depaoloc	09/29/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804976	Photos for Insp. #699804975	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874712