

Inspection Photos

September 26, 2022

Operator: Vision Energy LLC - #10770

Location ID: 322436

Location Name: Baldy Creek-Federal-67S90W /20NWNE

Inspection Document #: 702800744

Garfield County, CO

NWNE Section 20 T7S R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Baldy Creek-Federal-67S90W
/20NWNE
Location ID: 322436




Photo 1. Photo taken from the south shows an overview of the Location. Note unused tank and overgrown production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800744

Inspection Photos

Location Name: Baldy Creek-Federal-67S90W
/20NWNE

Location ID: 322436



Photo 2. Photo shows unused production equipment at the north of the Location.



Photo 3. Photo shows an unused horizontal separator on Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800744

Inspection Photos

Location Name: Baldy Creek-Federal-67S90W
/20NWNE

Location ID: 322436



Photo 4. Photo taken from the north of the Location shows an example of unmarked anchor. All anchors on Location are unmarked.



Photo 5. Photo taken from the north of the Location shows an example of trash/debris.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800744

Inspection Photos
Location Name: Baldy Creek-Federal-67S90W
/20NWNE
Location ID: 322436



Photo 6. Photo taken from the north of the Location shows trash/debris. Photo also shows sediment deposition from the nearby cut slope and erosion occurring to the fill slope from stormwater flows coming off the cut.



Inspection Photos

Location Name: Baldy Creek-Federal-67S90W
/20NWNE

Location ID: 322436




Photo 7. Photo taken from the north of the Location shows the eroding cut slope.



Photo 8. Photo taken from the north of the Location shows rill erosion occurring on the eroding cut slope.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800744

Inspection Photos
Location Name: Baldy Creek-Federal-67S90W
/20NWNE
Location ID: 322436



Photo 9. Photo from the center of the Location shows an overview of the eroding cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800744

Inspection Photos
Location Name: Baldy Creek-Federal-67S90W
/20NWNE
Location ID: 322436



Photo 10. Photo taken from the south of the Location shows the slope/contour in the reference area (blue arrow) and the start of the Location cut slope (red arrow). The cut slope is eroding and undercutting into undisturbed areas above the cut exposing roots.



Photo 11. Photo taken from the south of the Location shows the cut slope is eroding and undercutting into undisturbed areas above the cut exposing roots.



Inspection Photos

Location Name: Baldy Creek-Federal-67S90W
/20NWNE

Location ID: 322436



Photo 12. Photo shows an example of Canada and bull thistle, CO List B Noxious Weeds common throughout the Location.



Photo 13. Photo shows an example of houndstongue, a CO List B Noxious Weed common throughout the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800744