

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/22/2022

Submitted Date:

09/30/2022

Document Number:

696105465

FIELD INSPECTION FORMLoc ID 320547 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286687	WELL	PR	04/01/2022	OW	001-09567	MORRISON 16-1	RI
320547	LOCATION	AC			-	MORRISON-61S68W 1SESE	RI

General Comment:

This is an Interim Reclamation and Stormwater Inspection for API Well #001-09567.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: During this inspection COGCC Staff observed no visible sign at wellhead; there was a sign located approximately 15' south of wellhead within a pile of pipe fencing. Refer to inspection photos.

Corrective Action: Install sign to comply with Rule 605.d.

Date: 10/31/2022

Good Housekeeping:

Type WEEDS

Comment: During this inspection COGCC Staff observed weedy annual vegetation (e.g. russian thistle) located throughout the location. Refer to inspection photos.

Corrective Action: Comply with Rule 606.

Date: 10/14/2022

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: #

Comment: During this inspection COGCC Staff observed various pieces of equipment not currently being used, including but not limited to, a disassembled pump jack, fencing, pipe, platform, and a water tank. Upon desktop review, it appears some of the above mentioned equipment has not moved or been utilized since a 10/09/2019 inspection, reference document #693501609 and photo document #693501610. Refer to inspection photos.

Corrective Action: Comply with Rule 606.

Date: 10/31/2022

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	286687	Type:	WELL	API Number:	001-09567	Status:	PR	Insp. Status:	RI
Facility ID:	320547	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [At the time of this inspection, no erosion issues were observed at location or along the access road.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696105478	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5875514