



Response to: MACKINAW 12-28/KING 12-28 API #: 043-06201, 06211; FIR Doc#:695106751


Gas being vented or flared during non-upset condition without prior approval from COGCC. **THIS INSPECTION DUE TO COMPLAINT DOC #403164238, IN REFERENCE TO APPEARANCE OF VENTING.** CA: Immediately cease venting/flaring. PER RULE 903. Contacted Liz Harkins appearance of continuous venting out of the 2" on top of both tanks. It appears that the backside is plumbed to tank battery with a buried 1" line. At time of inspection the 1" line is closed.

-Upon phone notification by COGCC Field Inspector Tom Beardslee, Operator immediately dispatched crew to investigate suspect venting out of tank (casinghead valve plumbed to 1" upset condition vent line to tank was supposed to be in closed position). Crew advised that ball valve was leaking and took immediate action to bull plug valve and also capped 1" vent line at inlet and outlet; Also bull plugged vent stack on top of tank.




CONTINUED.....

Response to: MACKINAW 12-28/KING 12-28 API #: 043-06201, 06211; FIR Doc#:695106751



Tank labels (NFPA, Capacity, Contents). CA: Install sign to comply with Rule 605.h.
-Crew replaced worn placards and identified well names.



Unused equipment stored on location. CA: Remove unused equipment per Rule 606.
-Removed 28 damaged rods on ground that had been retrieved during a rod-part repair.