



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 5: impacted material/stained soil around wellhead from leaks and/or excessive rod oil use.		
Corrective Action:	clean up per Rule 1002.f2(c).	Date:	10/03/2022
Type	WEEDS		
Comment:	PHOTO 4: WEEDS AROUND WELLHEAD AND PUMPJACK.		
Corrective Action:	REMOVE WEEDS PER RULE 606.	Date:	10/03/2022

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:	ELECTRIC DRIVE		
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403179424	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5871197">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5871197</a>
695106763	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5871185">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5871185</a>