

Inspection Photos

Location Name: CAERUS PICEANCE LLC ASPEN RM-67S92W /10SENW

Location ID: 324224



Photo #7874 From entrance to location.



Photo #7875 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ASPEN RM-67S92W /10SENW

Location ID: 324224



Photo #7876 From entrance to location.



Photo #7877 Undesirable plant species in tank containment.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ASPEN RM-67S92W /10SENW

Location ID: 324224



Photo #7878 Undesirable plant species in tank containment.



Photo #7879 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ASPEN RM-67S92W /10SENW

Location ID: 324224



Photo #7880 Insufficient tracking BMP at entrance to location.