

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/30/2022

Submitted Date:

10/04/2022

Document Number:

700300441

**FIELD INSPECTION FORM**Loc ID 325310 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 31250

Name of Operator: FRITZ &amp; DIGMAN INC

Address: PO BOX 70024

City: ALBUQUERQUE State: NM Zip: 87197-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Vern		vern@walsheng.net	
Digman, Rebecca	505-379-8689	rcdigman@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214538	WELL	PR	12/01/2021	OW	067-06141	DAKOTA FEE 1	PR

**General Comment:**

Follow-up inspection, well shut in, no longer venting/flaring. FLIR video does show flowline at wellhead still leaking or leaking again. Weeds have grown up around equipment. No correctvie actions completed on access road, still no erosion control BMPs installed or repairs/mainenance done on access road, erosion and sediment migration have continued.

Form 1 still lists Rebecca Digman as principal agent and principal agent must be a recipient. Updating Form 1 information is responsibikity of operator.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:			
Corrective Action:	remove weeds and all trash/combustible materials from around equipment and production area	Date:	10/12/2022
Type	UNUSED EQUIPMENT		
Comment:	appears parts and unuseable fittings have been removed although difficult to fully see due to weed growth		
Corrective Action:		Date:	
Type	OTHER		
Comment:	appears gearbox is no longer leaking		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Flare	# 1		corrective date
Comment:	fire tube combustor not in use at time of inspection		
Corrective Action:		Date:	
Type: Pump Jack	#		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:	wellhead		
Corrective Action:		Date:	
Type: Prime Mover	#		

Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Weeds growing tall inside containment berms				
Corrective Action:	Control weeds anmd maintain berms per Rules 606 and 605.a(4) (old rules)				Date: 10/19/2022

**Venting:**

Yes/No	NO		
Comment:	no longer venting/flaring through combuster tube		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No action appears to have been taken on erosion on access road, no BMPOs present, no plan submitted. Visible erosion and sediment migration appear to have become worse. Erosion also occurring off ad and onto/along side access road.

Corrective Action: Immediately install erosion control BMPs and stabilize and repair access road. Also submit engineered plan by a erosion control supervisor or similar certified professional in order to comply with previous corrective actions (date retained) in regard to road design, stabilization and maintenance to comply with Rule 1002.f. Simply blading road has not worked in poast to achieve compliance.

Date: 05/31/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**

Survey Type: \_\_\_\_\_

Current Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: \_\_\_\_\_ Speed: \_\_\_\_\_ (mph) Direction From: \_\_\_\_\_ Weather: \_\_\_\_\_ Temperature: (F) \_\_\_\_\_

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
				Wellhead(s)
				Oil Tank(s)
				Flowline

Comment: [Flowline at wellhead leaking, see attachment section for link to FLIR video download. Same valve/fitting/pipinmg documented leaking in previous inspections](#)Corrective Action: [Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.](#)Date: 06/14/2022**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300450	FLIR gas leak flowline wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877496">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877496</a>
700300451	weeds around pumpjack and equipment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877497">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877497</a>
700300452	weeds in tank berms	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877498">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877498</a>
700300453	erosion/sediment coming off pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877499</a>
700300454	erosion off access road, no BMPS present	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877500</a>
700300455	erosion/sediment going off access road, no BMPs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877501</a>
700300456	erosion/washout along/across access road, no BMPs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877502">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877502</a>