

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403187156

Date Received:
10/04/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 17210
Name of Operator: CINNAMON CREEK OIL & GAS INC
Address: P O BOX 544
City: WALSH State: CO Zip: 81090

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Mills, Rick	719-324-5630/719-353-2523	rickmills000@gmail.com
Mills, Hellen		heleningle1221@yahoo.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 695106159
Inspection Date: 04/27/2022 FIR Submit Date: 04/28/2022 FIR Status:

Inspected Operator Information:

Company Name: CINNAMON CREEK OIL & GAS INC Company Number: 17210
Address: P O BOX 544
City: WALSH State: CO Zip: 81090

LOCATION - Location ID: 322268

Location Name: JOHNSON & STOCKER-619S70W Number: 2SWNE County: FREMONT
Qtrqtr: SWNE Sec: 2 Twp: 19S Range: 70W Meridian: 6
Latitude: 38.426080 Longitude: -105.190060

FACILITY - API Number: 05-043-00 Facility ID: 210091

Facility Name: JOHNSON & STOCKER Number: 1
Qtrqtr: SWNE Sec: 2 Twp: 19S Range: 70W Meridian: 6
Latitude: 38.426080 Longitude: -105.190060

CORRECTIVE ACTIONS:

1 CA# 161375

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.,(2).D. Date: 05/04/2022

Response: CA COMPLETED Date of Completion: 05/02/2022

Operator Comment: Maintenance was conducted on all equipment. Stained and impacted soils from oil spillage around the wellhead, under the flywheel and under the tank load-out valve were removed and replaced with clean soil. See photo Attachment.

COGCC Decision: _____

COGCC
Representative:

--

2 CA# 161376

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). THIS IS THE SECOND NOTICE IMMEDIATE ACTION IS REQUIRED.

Date: _____

Response: CA COMPLETED

Date of Completion: 05/04/2022

Operator
Comment:

The Johnson Stocker well is an early 1900 completion and has a welded surface string without ports for valve installations (typical of early Fremont County wells). Bradenhead valves cannot be installed on this wellhead. NOTE: a bradenhead test for another well was e-filed using an incorrect API number belonging to the Johnson-Stocker well and could not be retrieved for correction or deletion. The Form 17 for the Johnson Stocker well needs to be deleted, as it was not bradenhead tested and incorrectly submitted.

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator completed CA's to clean impacted soils around equipment and outside of berm on the Johnson-Stocker well on May 2, 2022. Another CA to conduct a bradenhead test could not be completed because of the the wellhead construction, showing welded surface casing without ports to install valves (typical completions in the early 1900's).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rick Mills

Signed: _____

Title: Owner

Date: 10/4/2022 4:49:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403187259	Corrective action photos
-----------	--------------------------

Total Attach: 1 Files