

Bradenhead inaccessible or not visible. CA: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). THIS IS THE SECOND NOTICE IMMEDIATE ACTION IS REQUIRED.

AREA OF IMPACTED SOIL AROUND WELLHEAD. CA: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 5-4-2022.



Photo shows the wellhead installed on the Johnson-Stocker well does not have valves on the surface string. All casing was welded together (typical of the early 1900's completions). A Form 17 for another well was submitted with the Johnson-Stocker API number and could not be retrieved or deleted from the e-files, but the Johnson-Stocker well cannot be fitted with valves to conduct the bradenhead test.

Impacted soil noted during inspection was dug up on May 02, 2022 and replaced with clean soil.

CA completed 5/02/22

AREA OF IMPACTED SOIL NEAR TANK CA: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 5-4-2022.



Impacted soil around equipment and tank was removed on May 02, 2022 and replaced with clean soil.

CA completed 5/02/22

AREA OF IMPACTED SOIL OUTSIDE OF BURM NEXT TO TANK BATTERY. CA: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 5-4-2022



Equipment maintenance was performed.

Stained soil outside of berm next to tank battery (noted during inspection) was removed and replaced with clean soil.

CA completed 5/02/22