

# Inspection Photos

September 26, 2022

Operator: Vision Energy LLC - #10770

Location ID: 322404

Location Name: Baldy Creek Unit-67S90W /17SENW

Inspection Document #: 702800746

Garfield County, CO

SENW Section 17 T7S R90W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Baldy Creek Unit-67S90W /17SENW

Location ID: 322404



**Photo 1.** Photo taken from the south shows an overview of the Location. Note vegetation, including noxious weeds growing around equipment.



**Photo 2.** Photo taken from the north shows an overview of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800746

## Inspection Photos

Location Name: Baldy Creek Unit-67S90W /17SEW

Location ID: 322404



**Photo 3.** Photo taken from the south of the Location shows the tank secondary containment is not in proper functioning condition. The base of the secondary containment area is completely grown in with vegetation. The berm is eroded and compromised by vegetation growing on it. Species pictured include bull thistle (List B Noxious) and mullein (List C Noxious).



**Photo 4.** Refer to Photo 3 comment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800746

Inspection Photos  
Location Name: Baldy Creek Unit-67S90W /17SENW  
Location ID: 322404



**Photo 5.** Photo taken from the north of the Location shows an example of unmarked anchor (red arrow). All anchors on Location are unmarked. Photo also shows noxious weeds houndstongue (List B) and mullein (List C).



**Photo 6.** Photo shows an example of trash/debris.

Inspection Photos  
Location Name: Baldy Creek Unit-67S90W /17SENW  
Location ID: 322404



**Photo 7.** Photo shows an example of trash/debris.



**Photo 8.** Photo shows an example of trash/debris.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800746

## Inspection Photos

Location Name: Baldy Creek Unit-67S90W /17SEW

Location ID: 322404



**Photo 9.** Photo shows where a hole/subsidence is occurring at a rock drain.



**Photo 10.** Photo shows a close-up of a hole/subsidence occurring at a rock drain.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800746

Inspection Photos  
Location Name: Baldy Creek Unit-67S90W /17SENW  
Location ID: 322404



**Photo 11.** Photo taken from the north shows an overview of the eroding cut slope.



## Inspection Photos

Location Name: Baldy Creek Unit-67S90W /17SENW

Location ID: 322404



**Photo 12.** Photo taken from the southwest of the Location shows the cut slope is eroding and undercutting into undisturbed areas above the cut exposing roots. Arrow indicates an undermined fence. Vegetation at the center of the cut is Canada thistle (List B Noxious). Note also pedestals around vegetation throughout slope.



**Photo 13.** Refer to Photo 12 comment.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800746