

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2022

Submitted Date:

09/27/2022

Document Number:

690103205

FIELD INSPECTION FORM

Loc ID 332660 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286197	WELL	SI	02/01/2022	OW	123-24155	LEAHY 43-9D	PA
332660	LOCATION	AC			-	HSR-LEAHY-64N67W 9NWSE	EG
482942	SPILL OR RELEASE	CL			-	Leahy 43-9D O SA TB	EG

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities									
Facility ID:	286197	Type:	WELL	API Number:	123-24155	Status:	SI	Insp. Status:	PA
Facility ID:	332660	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EG
Facility ID:	482942	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EG

Flowline			
#1	Type: Non-Well Site	of Lines	
<u>Flowline Description</u>			
Flowline Type:	Non-Well Site	Size:	2"
Variance:		Age:	
		Material:	Carbon Steel
		Contents:	
<u>Integrity Summary</u>			
Failures:		Spills:	
Coatings:		H2S:	
		Repairs Made:	
		Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:		Test Result:	
		Charted:	
<u>COGCC Rules (check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
<u>Comment:</u>	Well (Leahy 43-9D) has been plugged and abandoned; cut and cap operations have been completed. COGCC form 42 notice of start of plugging operations doc #403101760 received 07/11/2022. The wellhead flowline (OLF) has been removed/ AIP. COGCC form 42 notice of flowline abandonment completed doc #403170531 received on 09/19/2022. The on location dump and process flowlines at facility/ battery have been removed. No flowline risers were observed at the (PA) wellhead or facility/ battery areas. The facility/ tank battery has been decommissioned; tanks and equipment have been removed. (1) OOS gas meter run observed on the east side of location. A fenced excavation was observed at the battery/ wellhead areas; remediation work is in progress (historical). No Oxy personnel were on location at the time of inspection.		
Corrective Action:			Date:

COGCC Comments		
Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403170401 received on 09/21/2022: On September 19, 2022, historical soil impacts were discovered following flowline removal operations at the Leahy 43-9D location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	09/27/2022
As outlined on COGCC form 19 spill report Doc #403169176 received on 09/19/2022: On September 16, 2022, historical soil impacts were discovered following facility decommissioning operations at the Leahy 43-9D O SA facility location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	09/27/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690103209	Sigange and excavation at facility	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5878233
690103210	View of excavation and OOS GMR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5878234

690103211

Sigange at PA well

<http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5878235>