

Inspection Photos  
Location Name: UPRR 43 PAN AM I #5  
Location ID: 318212



Photo 1 Well sign



Photo 2 loc pic

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM I #5**  
**Location ID: 318212**



**Photo 3 non maintained BMP**



**Photo 4 improper BMP**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM I #5**  
**Location ID: 318212**



**Photo 5 inadequate BMP**



**Photo 6 contaminated stock pile BMP overloaded and sediment leaving BMP**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM I #5**  
**Location ID: 318212**



**Photo 7 Inadequate stockpile bmp**



**Photo 8 Inadequate stockpile BMP. BMP sediment loaded.**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM I #5**  
**Location ID: 318212**



**Photo 9 Inadequate stockpile BMP No liner underneath contaminated soil stock pile**



**Photo 10 Contaminated stock pile sign**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM I #5**  
**Location ID: 318212**



**Photo 11 location pic home are approx.. 150 to the west of stock pile and open excavatio,.**



**Photo 12 inadequate fencing around open excavation. Homes are approx..150 feet to the west. No BMP in place to control run on of water into excavation.**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM I #5**  
**Location ID: 318212**



**Photo 13 loc pic. Inadequate fence and birm.**



**Photo 14 loc pic. Inadequate fence and birm.**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM I #5**  
**Location ID: 318212**



**Photo 15 loc pic**



**Photo 16 loc pic**

**Inspection Photos**  
**Location Name: UPRR 43 PAN AM I #5**  
**Location ID: 318212**



**Photo 17 loc pic**