

Inspection Photos

API: 071-06630

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/4/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06630 | Date: 10/4/2022

Inspection Photos



Photo 1. The culvert outlet at the drainage crossing has eroded and has no outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06630 | Date: 10/4/2022

Inspection Photos



Photo 2. There is erosion occurring across the road and at the culvert outlet.



Inspection Photos



Photo 3. Facing northeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06630 | Date: 10/4/2022

Inspection Photos



Photo 4. There is erosion along the fill slope which needs additional BMP's



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06630 | Date: 10/4/2022