

# Inspection Photos

API: 055-06105

Operator: OXY USA INC

Inspection Date: 10/6/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06105 | Date: 10/6/2022

## Inspection Photos



**Photo 1.** Facing southeast ascending the hill toward the location. There has been grading performed which has pushed gravel material to the side which is now interfering with stormwater flow to the culvert which is at the red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06105 | Date: 10/6/2022



## Inspection Photos



**Photo 2.** Facing southeast ascending the hill toward the location. The graded material is loose and susceptible to erosion. There are no BMP's to prevent erosion along this long stretch of road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06105 | Date: 10/6/2022



## Inspection Photos



**Photo 3.** Facing southeast ascending the hill toward the location. There was no BMP's installed along the roadside where erosion had occurred and loose soils were pushed off the side which are susceptible to erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06105 | Date: 10/6/2022



## Inspection Photos



**Photo 4.** Facing southeast ascending the hill toward the location. There has been grading performed which has pushed gravel material to the side which is now interfering with previous BMP's. Red arrow points to rock check dam. There are also numerous noxious weeds in this area that have not been controlled.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 055-06105 | Date: 10/6/2022



## Inspection Photos



**Photo 5.** Further along the road is another area where erosion of the road side had occurred and loose soils have been pushed into this area. This area needs to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06105 | Date: 10/6/2022



## Inspection Photos



**Photo 6.** Facing northwest at the location. There is various unused equipment and trash debris stored in this area. The damaged culverts and degraded wattle are now stored in this area and need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06105 | Date: 10/6/2022



## Inspection Photos



**Photo 7.** Facing back southeast at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06105 | Date: 10/6/2022