

Inspection Photos

API: 055-06037

Operator: OXY USA INC

Inspection Date: 10/6/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06037 | Date: 10/6/2022

Inspection Photos



Photo 1. The cattle guard is damaged and needs to be repaired or removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06037 | Date: 10/6/2022

Inspection Photos



Photo 2. There has been grading performed along the road however, gravel material has been pushed off the road causing additional disturbance



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06037 | Date: 10/6/2022

Inspection Photos



Photo 3. Facing southeast toward the well site. The gravel debris still remains and was just pushed out disturbing interim reclamation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06037 | Date: 10/6/2022

Inspection Photos



Photo 4. There is gravel debris from a pile stored on location. The leftover gravel needs to be removed. This disturbance area needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06037 | Date: 10/6/2022

Inspection Photos



Photo 5. The degraded wattles were removed. There are still noxious weeds in this area that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06037 | Date: 10/6/2022