

Inspection Photos

API: 055-06316

Operator: OXY USA INC

Inspection Date: 10/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 10/6/2022

Inspection Photos



Photo 1. Facing south along the access road. There are signs of erosion along the steep grade of the road. Stormwater should be diverted off the road to reduce erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 10/6/2022

Inspection Photos



Photo 1. Facing back north the steep grade of access road. This road has eroded in the past and is susceptible to erosion. BMP's need to be installed along the road to prevent erosion e.g. water bars, diversion ditch, checkdams.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 10/6/2022

Inspection Photos



Photo 2. Sign is posted at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 10/6/2022

Inspection Photos



Photo 4. There was an audible noise coming from this area. Does not appear to have been fixed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 10/6/2022

Inspection Photos




Photo 5. There were bubbles coming out of the water which indicates a leak at the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06316 | Date: 10/6/2022

Inspection Photos



Photo 6. There are noxious weeds at the southwest corner of the location.
Red arrow → Canada thistle

