

## Inspection Photos

Location Name: CAERUS PICEANCE LLC LAST DANCE-66S92W /34SESE

Location ID: 334620



**Photo #7964 From entrance to location.**



**Photo #7965 From entrance to location.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC LAST DANCE-66S92W /34SESE

Location ID: 334620



Photo #7966 From entrance to location.



Photo #7967 Multiple places with undesirable plant species.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC LAST DANCE-66S92W /34SESE

Location ID: 334620



Photo #7972 Multiple places with undesirable plant species.



Photo #7973 Multiple places with undesirable plant species.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC LAST DANCE-66S92W /34SESE

Location ID: 334620



**Photo #7974** Multiple places with undesirable plant species.




**Photo #7970** Location lacks stabilization.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC LAST DANCE-66S92W /34SESE

Location ID: 334620



**Photo #7971** Location lacks stabilization.



**Photo #7976** Insufficient tracking BMP located at entrance to location.