

Inspection Photos

API: 055-06301

Operator: CAPTUREPOINT LLC

Inspection Date: 10/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 10/6/2022

Inspection Photos



Photo 1. Facing west at the entrance of the Gas Plant. There are noxious weeds along the road that need to be controlled. Red arrow → Diffuse knapweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 10/6/2022

Inspection Photos



Photo 2. Facing northeast at the Gas Plant. There are noxious weeds along the road that needs to be controlled. Red arrow → Diffuse knapweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 10/6/2022

Inspection Photos



Photo 3. Facing southwest along the access road. There are noxious weeds that need to be controlled. Red arrow → Diffuse knapweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 10/6/2022

Inspection Photos



Photo 4. Facing northwest along the road. The road has been regraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 10/6/2022

Inspection Photos



Photo 5. Facing southwest along the access road. There are noxious weeds that need to be controlled. Red arrow → Mullein.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 10/6/2022

Inspection Photos



Photo 6. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 10/6/2022

Inspection Photos



Photo 7. Facing toward the wellhead. There are noxious weeds at the location that need to be controlled. Red arrow → Diffuse knapweed



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06301 | Date: 10/6/2022