

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2022

Submitted Date:

10/11/2022

Document Number:

702500579

FIELD INSPECTION FORM

Loc ID 320863 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 1001 17TH STREET STE 1160
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		Inspections@catamountep.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205261	WELL	PR	03/01/2020	CBM	007-06140	PARGIN MOUNTAIN UNIT 11	PR
456218	WELL	PR	12/20/2019	CBM	007-06330	EBC 9	PR
456219	WELL	PR	12/24/2019	CBM	007-06331	EBC 10	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume		corrective date
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Chemical container near #10 separator. Spill prevention is nearly full from stormwater and does not have adequate capacity to prevent spills from chemical container. (IMG 03).			
Corrective Action:	Maintain BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.			Date: 10/16/2022
Type: Ancillary equipment	# 5			
Comment:	Telemetry, 2 electric boxes with solar panel, portable toilet, produced water transfer house.			
Corrective Action:				Date:
Type: Prime Mover	# 3			
Comment:	Gas powered			
Corrective Action:				Date:
Type: Gas Meter Run	# 3			
Comment:	Gas meter calibrations are within the last year.			
Corrective Action:				Date:
Type: Bradenhead	# 3			
Comment:	Bradenheads are accessible.			
Corrective Action:				Date:
Type: Flow Line	# 10			
Comment:	2" line from Pargin Mountain wellhead to separator, 2 4" and 2 2" lines from #9 and #10 wellheads to separators, 3 lines from separators to produced water tanks, 2 2" lines from separators to #9 and #10 gas powered prime movers.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 3			

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:	Separator vent stacks are screened properly.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		37.146738,-107.382172
Comment:	2 above ground produced water tanks, each with 500 bbl capacity.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Plastic barrier with liner material.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 205261 Type: WELL API Number: 007-06140 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 456218 Type: WELL API Number: 007-06330 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 456219 Type: WELL API Number: 007-06331 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Ditches	Fail			
Berms	Pass					
Ditches	Pass					
Gravel	Pass					
Culverts	Pass					

Comment: Sediment on road (IMG 04). Sediment appears to originate from up gradient erosion channel. Ditch is filled with sediment and not maintained. Access roads must be operated in a manner that minimizes erosion and transport of sediment.

Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C

Date: 11/11/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500580	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883613