

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2022

Submitted Date:

10/11/2022

Document Number:

702500589

FIELD INSPECTION FORM

Loc ID 320856 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 1001 17TH STREET STE 1160
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-----------------------------|--|
| , General | | Inspections@catamountep.com | All SW field inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 205244 | WELL | PR | 01/01/2020 | CBM | 007-06122 | BULL CREEK FEDERAL A 1 | PR |

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | Area | Volume | | corrective date |
|---------------------------------|--|--------|--|-----------------|
| Type: Ancillary equipment | # 1 | | | |
| Comment: | Telemetry | | | |
| Corrective Action: | | | | Date: |
| Type: Bradenhead | # 1 | | | |
| Comment: | Bradenhead is accessible. | | | |
| Corrective Action: | | | | Date: |
| Type: Flow Line | # 3 | | | |
| Comment: | 2" line from wellhead to separator, 2" line from separator to gas powered prime mover, line from separator to produced water off location. | | | |
| Corrective Action: | | | | Date: |
| Type: Prime Mover | # 1 | | | |
| Comment: | Gas powered. | | | |
| Corrective Action: | | | | Date: |
| Type: Vertical Heated Separator | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | Gas meter calibration is within the last year. | | | |
| Corrective Action: | | | | Date: |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Bird Protectors | # 1 | | | |
| Comment: | Separator vent stack is screened | | | |
| Corrective Action: | | | | Date: |
| Type: Pump Jack | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 205244 Type: WELL API Number: 007-06122 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Sediment on access road originating from up gradient erosion channel, (IMG 04, IMG 05). Ditch is filled with sediment. Access road BMP's not maintained. Erosion channel at location entrance (IMG 03). Location BMP's not maintained. Location and access roads must be operated in a manner that minimizes erosion and transport of sediment.

Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C

Date: 11/11/2022

Pits: NO SURFACE INDICATION OF PIT