

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2022

Submitted Date:

10/05/2022

Document Number:

697601895

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Gorka, Ray		RGorka@kpk.com	KPK environmental
, KPK		cogcc@kpk.com	All Inspections
-, Marcom		primarycontractor@marcomllc.net	
Meis, Craig		cmeis@kpk.com	KPK Environmental

General Comment:

This is an environmental inspection for Spill ID 482971 Greeley National Bank B-#1. The operator has begun work at the excavation (78'x64'x16') at the spill location. Staining is visible within the excavation. Groundwater was encountered at approximately 16 feet depth and is in contact with hydrocarbons.

Any corrective actions from previous forms and inspections that have not been addressed are still applicable.

Photos are attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: Yes

Comment:

Multiple Spills and Releases?

Fencing/:					
Type	OTHER				
Comment:	Fencing around the perimeter of the excavation is adequate.				
Corrective Action:				Date:	

Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	

Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Adequate		
Comment	Contaminated stockpile is adequately lined and bermed and is continuously being hauled off location.			
Corrective Action				Date:

Spill/Remediation:

Comment:	Excavation work has begun at the spill location. Staining is visible within the excavation. Groundwater was observed in contact with gross free product.		
Corrective Action:	Pursuant to Rule 912.b.(6) Operator is required to submit a Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. Operator shall provide an initial Form 27.		Date: 10/19/2022

Emission Control Burner (ECB):	_____
Comment:	_____
Pilot:	_____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403188897	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5879150
697601896	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5879149