

Final Reclamation Inspection

August 7th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 330540

Inspection Document #: 701900567

NWNE Section 10 T5N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wacker 31-10
Location ID: 330540



Photo 1. 2020 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Wacker 31-10
Location ID: 330540



Photo 2. Overview photo of the well pad, access road and reference area taken from the southern edge facing north using a drone. Note: well pad and access road appear consistent with adjacent crop reference area.

Inspection Photos
Location Name: Wacker 31-10
Location ID: 330540



Photo 3. Overview photo of the tank battery taken at ground level from the northern edge facing south. Note: new DCP Midstream riser exists at the disturbance.

Inspection Photos
Location Name: Wacker 31-10
Location ID: 330540



Photo 4. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Wacker 31-10
Location ID: 330540



Photo 5. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery falls within a corner crop area but has higher density of kochia and does not appear consistent with the other corner crop areas (see photo 6).

Inspection Photos
Location Name: Wacker 31-10
Location ID: 330540



Photo 6. Tank battery reference are.