

Inspection Photos

October 10, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 427776

Location Name: MDP #21 Pad /13A-19-691

Inspection Document #: 702800790

Garfield County, CO

NESW Section 19 T6S R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MDP #21 Pad /13A-19-691
Location ID: 427776



Photo 1. Photo shows the reclaimed access road to the southeast of the Location. Vegetation is dominated by annual weeds. Fourwing saltbush (native shrub) is also present.



Photo 2. Refer to Photo 1 comment.

Inspection Photos
Location Name: MDP #21 Pad /13A-19-691
Location ID: 427776



Photo 3. Photo taken from the Location entrance to the east shows an overview of the reclaimed Location.



Photo 4. Photo taken from the north shows an overview of the reclaimed Location and access road (red arrow).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800790

Inspection Photos

Location Name: MDP #21 Pad /13A-19-691

Location ID: 427776



Photo 5. Photo shows an example of an area with poor perennial establishment and dominance of annual undesirable plant species and noxious weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800790

Inspection Photos
Location Name: MDP #21 Pad /13A-19-691
Location ID: 427776



Photo 6. Photo shows an example of an area where shrubs are well established but the herbaceous understory is dominated by the annual noxious weed, cheatgrass. Perennial herbaceous plants are absent.



Photo 7. Photo shows dense establishment of cheatgrass and absence of desirable perennials.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800790

Inspection Photos
Location Name: MDP #21 Pad /13A-19-691
Location ID: 427776



Photo 8. Photo shows a patch of Canada thistle, a CO List B Noxious Weed.



Photo 9. Photo shows stormwater control measures and dense establishment of cheatgrass and kochia and absence of desirable perennial species.



Inspection Photos

Location Name: MDP #21 Pad /13A-19-691

Location ID: 427776



Photo 10. Photo shows stormwater control measures and vegetation establishment. Red circles indicate tamarisk, a CO List B Noxious Weed.



Photo 11. Photo shows stormwater control measures and vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800790

Inspection Photos
Location Name: MDP #21 Pad /13A-19-691
Location ID: 427776



Photo 12. Photo shows stormwater control measures and vegetation establishment.



Photo 13. Photo shows stormwater control measures and vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800790

Inspection Photos
Location Name: MDP #21 Pad /13A-19-691
Location ID: 427776



Photo 14. Photo shows stormwater control measures and vegetation establishment.



Photo 15. Photo shows stormwater control measures and vegetation establishment.

Inspection Photos

Location Name: MDP #21 Pad /13A-19-691

Location ID: 427776



Photo 16. Photo taken to the west of the Location shows the perimeter fence is non-functioning. It appears to have been cut.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800790

Inspection Photos

Location Name: MDP #21 Pad /13A-19-691

Location ID: 427776



Photo 17. Photo taken to the west of the Location shows the reference area vegetation community is dominated by pinyon and juniper with an Indian ricegrass understory.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800790