

# Inspection Photos

API: 055-06012

Operator: OXY USA INC

Inspection Date: 10/6/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06012 | Date: 10/6/2022

## Inspection Photos



**Photo 1.** Drone aerial photo of the location showing the excavated areas of the remediation project.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06012 | Date: 10/6/2022

## Inspection Photos



**Photo 2.** Facing northwest toward the location.



## Inspection Photos



**Photo 3.** Facing where tank was located. Impacted soil were excavated from this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06012 | Date: 10/6/2022

## Inspection Photos



**Photo 4.** Standing at the shallow pit facing southeast.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06012 | Date: 10/6/2022

## Inspection Photos



**Photo 5.** There is an excavation area at the center of the location.



## Inspection Photos



**Photo 6.** Southwest side of the location facing east.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06012 | Date: 10/6/2022

## Inspection Photos



**Photo 7.** There is impacted soils being stored at the north side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06012 | Date: 10/6/2022