

# Inspection Photos

API: 061-06023

Operator: WESTERN OPERATING COMPANY

Inspection Date: 10/12/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022

## Inspection Photos



**Photo 1.** Drone aerial photo facing west toward the battery and wellsite. There is a remediation project in process.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022



## Inspection Photos



**Photo 2.** Facing southwest toward the tank battery facility. The tank was removed and soils have been excavated in this area. Remediation project: 20712



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022



## Inspection Photos



**Photo 3.** Facing south toward the east side of the tank battery location. A berm was installed around the perimeter of the soil piles. Berms are not compacted and may not withstand heavy precipitation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022



## Inspection Photos



**Photo 4.** The berms around the soil piles have been constructed larger but were not compacted. Also, no liner was observed under the contaminated soils. Contaminated soils should be removed and properly disposed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022

## Inspection Photos



**Photo 5.** Facing north at the southwest side of the tank battery location. Additional BMP's should be installed on the down gradient side shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022



## Inspection Photos



**Photo 6.** Facing southwest toward the area where the spill occurred. Remediation project: 20712. Some areas have been excavated more than other areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022

## Inspection Photos



**Photo 7.** Facing northeast at the down gradient side of the spill area. Straw wattles have been installed along the edge of the disturbance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022



## Inspection Photos



**Photo 8.** Located at the western side of the spill area. There is an excavated hole at this area approximately 12'x12'6'. There are still areas of oil stained soils at the surface (Bottom left) and 2ft. Down into the excavation area (right photo). Further excavation is needed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022



## Inspection Photos



**Photo 9.** Insulators have been put on the posts for the electric perimeter fence.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022



## Inspection Photos



**Photo 10.** Drone aerial photo facing east toward the battery and remediation project.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06023 | Date: 10/12/2022