

Inspection Photos

API: 061-06020

Operator: WESTERN OPERATING COMPANY

Inspection Date: 10/12/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06020 - Date: 10/12/2022

Inspection Photos



Photo 2. Facing west toward the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06020 - Date: 10/12/2022

Inspection Photos



Photo 2. The fence at the tank battery has been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06020 - Date: 10/12/2022

Inspection Photos



Photo 3. A secondary containment berm has been installed around the tank battery. The berm still needs to be compacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06020 - Date: 10/12/2022

Inspection Photos



Photo 4. Facing toward the pumpjack. There is stormwater runoff transporting sediment offsite. Previous corrective action not completed to install BMP's.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06020 - Date: 10/12/2022

Inspection Photos



Photo 5. The sign at the wellhead does not reflect current Operator.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06020 - Date: 10/12/2022