

# Inspection Photos

API: 061-06891

Operator: KUENZLER & FLORA RESERVE COMPANY

Inspection Date: 10/12/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06891 - Date: 10/12/2022

## Inspection Photos



**Photo 1.** Facing north along the access road. There is no vegetation growth along the two track road which indicates possible soil compaction. Soils must be decompacted by cross-ripping to at least 18 inches.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06891 - Date: 10/12/2022

## Inspection Photos



**Photo 2.** Facing northeast at the location. This where the pumpjack was removed was not leveled out. There are oil stained soils shown at red arrow and gravel remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06891 - Date: 10/12/2022

## Inspection Photos



**Photo 3.** Facing toward the area where the pumpjack was located. Soils were not leveled out and decompacted. There is oil stained soil at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06891 - Date: 10/12/2022

## Inspection Photos



**Photo 4.** Facing north at the location. This is the area of the former pit which has no vegetation or weeds which is a concern of possible impacted soils.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06891 - Date: 10/12/2022

## Inspection Photos



**Photo 5.** There is some remnant scrap metal pieces that remain and need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06891 - Date: 10/12/2022

## Inspection Photos



**Photo 6.** Facing south toward the area of no vegetation which is approx. 100'x75'.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06891 - Date: 10/12/2022